





R.b.	Naziv iz dostavljene specifikacije	Vrsta opreme	Proizvođač	Model i tipa	Trenutno stanje opreme na terenu 22.11.2018.	Ocena trenutnog stanja opreme	Notes	God. proiz. ili aktiv.
4	Metal detektor sa transporterom, marke CINTEX	Metal detektor	Cintex	CS 2060	 	Dobro	<i>Impossible to be calibrated. Companies Trim doo and Mos doo unsuccessfully tried to calibrate and certify the machine. Audits were passed with rented metal detector.</i>	2006
18	Higijenska stanica (za dezinfekciju ruku i cizama), marke STAR CLEAN, godina proizvodnje 2008	Higijenska stanica za obuću i ruke	Star Clean	1600		Veoma dobro	<i>Main circuit board for one half of the machine is burned. New one will be printend and installed. A new pair of roller brushes also needed.</i>	2008
19	Rashladni uredjaj	Ledomat	ZIEGRA Eismaschinen GmbH	UBE 3500-2	 	Dobro	<i>From time to time machine is malfunctioning for unknown reasons. Companies Frigovent doo and Rotech El were engaged to try to resolve this issue. Currently, machine is not reliable.</i>	2006
21	Transportne trake	Transportne trake	-	-	-	Dobro		2008
22	Podna vaga za palete, marke DIBAL	Podna vaga	Dibal	-	-	Dobro	<i>Machine is not complete. Only main steel frame was sent to Serbia.</i>	2008
25	Boca vazdušnog kompresora, drobilica i mikser	Drobilica	Gernal Menen	NK 5 KL	 	Loše	<i>Visible signs of rust and transport damage. Inside mechanism of machines completely damaged.</i>	1983
26		Vakumski mikser	Kilia	-		Veoma loše		1995

28	Sudopera od prohroma, marka ROSER	INOX sudopera sa 4 slavine	Roser	-			Veoma dobro	<i>Sink is installed and in use. Another one needed. Offer requested from PakPromet.</i>	2008
31	Transportne trake sa pripadajucim delovima, marke Ulma, Scanvaegt	Trake za trakaste transportere	Ulma+Scanvaegt Systems	-			Dobro	<i>Two chain transport bands are part of ULMA Scorpius line. Visible signs of heavy transport damage on both machines. Manufacturer plates missing.</i>	2008
32	Podna vaga za merenje paleta, marke DIBAL	Podna vaga	Dibal	-			Dobro	<i>Unable to be indentified.</i>	2007
33	Ventilatori i kondenzatori, marke Wolf	Kaloriferi	Wolf	LH 25-3			Loše		2008
34		Kondezatori	-	-			Veoma loše		2008
36	Mašina za dekalifikaciju, godina proizvodnje 2013	Oprema za demineralizaciju vode	-	-			Dobro	<i>Signs of rust. Without any succes unit was tested. New one is bought and currently in use **Ova je i procenjena verovatno.</i>	2013
37	Postolje za vagu, marke DIBAL	Postolje za vagu	-	-			Veoma dobro	<i>Three stainless steel stands, good condition, currently in</i>	2008
38	Vaga sa štampancem, marke DIBAL	Vaga sa štampancem	Dibal	LP 3000			Veoma loše	<i>Without any succes, scales were tested by company Brotehna doo. It is impossible to calibrate and certify weighing units. Visible signs of rust.</i>	2008
39	Valjci rezervni - paket	Valjci za transportnu traku	-	-			Dobro		2008
40	Vaga marke ROBBE 9306	Podna vaga	Robbe	9306			Dobro		2007
41	Mašina za čišćenje cizama, marke Star clean, godina proizvodnje 2008	Higijenska stanica za obuću	Roser	12480			Dobro	<i>Machine is in working condition.</i>	2008

1	Metal detektor marke DIBAL, godina proizvodnje 2006	Metal detektor	Dibal	MD 3300	 		Loše	Visible signs of rust. Main circuit board burned. Manufacturer plate missing	2006
2	Vaga sa monitorom i trakom, marke aew DELFORD SYSTEMS, godina proizvodnje 2001	Vaga sa monitorom i transportnom trakom	AEW Delford Systems	INT Delford			Loše		2001
3	Dodatna traka za veliku ribu, marke MK-ENGINEERING, godina proizvodnje 2007	Transportna traka	MK Engineering	-			Veoma loše	To be assembled.	2007

Ukupno početna cena opreme ~~68100 €~~ 32,866 €

