

Number	Name from specification	Equipment type	Producer	Model and type	Current state of the equipment (Photos)	Mark of current state of the equipment	Notes	Production year or year of contract activation
5	Packing machine with thermo-foil, - manufacturer TECHNOTRIP, production year 2007	Packing machine with thermo-foil	Tecnotrip	-		Bad	<i>Minor signs of transport damage. Manufacturer plate missing. Stainless steel</i>	2007
6	Packing machine with thermo-foil, - manufacturer ULMA SCORPIUS 600, production year 2006	Packing machine with thermo-foil	ULMA	Scorpius 600		Very good	<i>Connecting cables from machine to transport band are cutted. On one of the</i>	2006
7	Flow packing machine, - manufacturer ULMA PV 550, production year 2006	Flow packing machine	ULMA	PV 550		Bad	<i>Machine was visually inspected by official ULMA technician. In his opinion,</i>	2006
53	Vacuum pump BUSCH RA 0302D523ULXZ, production year 2013	Vacuum pump	Busch	RA 0302	-	Bad	<i>Visible signs of heavy transport damage and oil leaks. Pumps are sent to ENERGLINK in</i>	2013

**Total equipment** 70580 € **34,063 €**

